

TECHNICAL BULLETIN

Profil: General

TB001235

Publié Septembre 2009

Compilé par C.B.

Indesit Company, Service Department

Titre : Démontage de la sécurité de porte Istantaneo

Produits concernés



Toutes les machines à laver et lavante séchante Ariston / Hotpoint avec sécurité de porte Istantaneo

Description du problème



Le démontage du bloc de verrouillage de la porte doit être fait avec soin afin de ne pas causer des fissures dans le bloc de raccordement d'étanchéité.

Intervention à effectuer

1. L'opération de démontage du connecteur est faite en utilisant un petit outil (ex : un tournevis) pour libérer le connecteur de la sécurité de porte, sinon il pourrait rompre le crochet du connecteur





2. Avant d'insérer un nouveau connecteur, vous devez vérifier que le crochet ne se décompose pas. La rupture du joint crochet peut entraîner le détachement du lien de raccordement et le dysfonctionnement de la machine.



Information

During production at the Radomsko Factory (30) Poland and Comunanza factory (80) Italy an alternative door Interlock is being fitted

The original (Bitron Type) interlock *Fig 1* is secured to the front panel by 2 x T15 screws (C00065185).
The alternative (Rold Type) interlock *Fig 2* is held in place on the front panel by 2 x plastic locating pips.

**Intervention Required**

NOTE:

These door interlocks are interchangeable